| Component Name | Remaining Life | Current Cost | \vdash | 0 2011 | 1 2012 | 2 2013 | 3 2014 | 4 2015 | 5 2016 | 6 2017 |
|--|----------------|--------------|--------------|------------------|------------------|------------------|------------------|-----------|------------------|------------------|
| Painting - Bldg, Doors, Trim (ph1) | 0 | \$25.000 | + | | 2012 | 2013 | 2014 | 2013 | 2010 | 29,851 |
| Painting - Bldg, Doors, Trim (ph1) Painting - Bldg, Doors, Trim (ph2) | 1 | \$20,000 | \vdash | 25,000 | 20,600 | | | | | 29,001 |
| Painting - Bidg, Doors, Trim (ph2) Painting - Bidg, Doors, Trim (ph 3) | 2 | \$20,000 | \vdash | | 20,000 | | | | | |
| Painting - Bidg, Doors, Trim (pir s) Painting - Seal/Stain Decks | 0 | | \vdash | 2.045 | | 4.000 | | 2 202 | | 2.000 |
| | 23 | \$3,015 | \vdash | 3,015 | | 4,890 | | 3,393 | | 3,600 |
| Roofing - Ph 1 | | \$18,000 | \vdash | | | | | | | |
| Roofing Ph 2 | 24 | \$18,000 | ₩. | | | | | | | |
| Roofing Ph 3 | 25 | \$18,000 | ₩. | | | | | 4 = 00 | | |
| Gutters - Additions/Repair/Rep | 4 | \$4,000 | \vdash | | | | | 4,502 | | |
| Lighting - Stairwell/Hallways Ph 1 | 23 | \$6,000 | \vdash | | | | | | | |
| Lighting - Stairwell/Hallways Ph 2 | 24 | \$5,000 | \vdash | | | | | | | |
| Lighting - Stairwell/Hallways Ph 3 | 25 | \$5,000 | \sqcup | | | | | | | |
| Carpeting - Outdoor Stairwell, Replace | 1 | \$11,000 | Ш | | 11,330 | | | | | |
| Parking Lots - asphalt (ph 1) | 13 | \$17,000 | Ш | | | | | | | |
| Parking Lots - Asphalt (ph 2) | 14 | \$12,000 | Ш | | | | | | | |
| Parking Lots - Asphalt (ph 3) | 15 | \$17,000 | | | | | | | | |
| Parking Lots - Curb and Gutters Ph 1 | 23 | \$18,000 | Ш | | | | | | | |
| Parking Lots -Curb and Gutters Ph 2 | 24 | \$15,000 | ШΤ | | | | | | | |
| Parking Lots - Curb and Gutters Ph 3 | 25 | \$18,000 | | | | | | | | |
| Parking Lots - Sealcoating/striping | 1 | \$3,979 | | | 4,098 | | | 4,478 | | |
| Irrigation - Valve Boxes, Replace | 3 | \$4,100 | | | | | 4,480 | | | |
| Irrigation - Backflow Preventer, Replace | 8 | \$3,000 | | | | | | | | |
| rrigation - Controller/Clock, Replace | 3 | \$1,000 | | | | | 1,093 | | | |
| Landscaping - Trees/Shrubs (ph 1) | 3 | \$2,500 | | | | | 2,732 | | | |
| Landscaping - Trees/Shrubs (ph 2) | 4 | \$2,000 | | | | | , - | 2,251 | | |
| Landscaping - Trees/shrubs (ph 3) | 5 | \$2,000 | | | | | | _,; | 2,319 | |
| Lighting - walkways Ph 1 | 23 | \$4,000 | | | | | | | 2,0.0 | |
| Lighting - walkways Ph 2 | 24 | \$4,000 | | | | | | | | |
| Lighting - walkways Ph 3 | 25 | \$4,000 | \vdash | | | | | | | |
| Sidewalks - concrete (ph 1) | 23 | \$18,000 | \vdash | | | | | | | |
| Sidewalks - concrete (ph 2) | 24 | \$15,000 | \vdash | | | | | | | |
| Sidewalks - concrete (ph 3) | 25 | \$18,000 | \vdash | | | | | | | |
| Dumpster Enclsoures - Stain/power wash | 1 | \$799 | \vdash | | 823 | | | 899 | | |
| Dumpster Encisoures - Stain/power wash | | | \vdash | | 023 | | | 099 | | |
| Dumpster Enclsoure - Replace (Ph 1) | 13 | \$5,000 | \vdash | | | | | | | |
| Dumpster Enclosure - Replace Ph 2 | 14 | \$5,000 | \vdash | | | | | | | |
| Dumpster Enclosure - Replace Ph 3 | 15 | \$5,000 | ₩. | | | | | | | |
| Entryway sign - Replace | 23 | \$4,500 | \vdash | | | | | | | |
| Dryer Vents - Clean out | 1 | \$799 | \sqcup | | 989 | | | 1,080 | | |
| | | | ₩ | | | | | | | |
| | | | | | | | | | | |
| Estimated Total Cost | | \$352,692.00 | Д | \$28,015 | \$36,028 | \$4,890 | \$8,305 | \$16,604 | \$2,319 | \$33,451 |
| Annual Cash Balances | | | \vdash | | | | | | | |
| Beginning Cash Balance | + | | \vdash | | | \$156,929 | \$177,039 | \$193,734 | \$235,824 | \$294,363 |
| | | | | | | | | | | |
| Reserve Contribution | | | - | | | \$25,000 | \$25,000 | \$25,000 | \$25,000 | \$25,000 |
| Interest Income | | | \vdash | | | \$0 | \$0 | \$33,695 | \$35,857 | \$0 |
| Expenditures | | | \vdash | | £450.000 | \$4,890 | \$8,305 | \$16,604 | \$2,319 | \$33,451 |
| Ending Cash Balance | | | \vdash | | \$156,929 | \$177,039 | \$193,734 | \$235,824 | \$294,363 | \$285,912 |
| | | | | | | | | | | |
| | | | | | | | | | | |

| Component Name | 2018 | | | | | | | | | 2027 |
|--|-----------|--------------------|-----------|-----------|-----------|----------------------|-------------|-----------|-------------|--|
| | | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 |
| Painting - Bldg, Doors, Trim (ph1) | | | | | | 35,644 | | | | <u> </u> |
| Painting - Bldg, Doors, Trim (ph2) | 24,597 | | | | | | 29,371 | | | <u> </u> |
| Painting - Bldg, Doors, Trim (ph 3) | | 25,335 | | | | | | 30,252 | | |
| Painting - Seal/Stain Decks | | 3,819 | | 4,052 | | 4,299 | | 4,560 | | 4,838 |
| Roofing - Ph 1 | | | | | | | | | | |
| Roofing Ph 2 | | | | | | | | | | |
| Roofing Ph 3 | | | | | | | | | | |
| Gutters - Additions/Repair/Rep | | | 5,219 | | | | | 6,050 | | |
| Lighting - Stairwell/Hallways Ph 1 | | | | | | | | | | |
| Lighting - Stairwell/Hallways Ph 2 | | | | | | | | | | |
| Lighting - Stairwell/Hallways Ph 3 | | | | | | | | | | |
| Carpeting - Outdoor Stairwell, Replace | | | 14,353 | | | | | | | |
| Parking Lots - asphalt (ph 1) | | | , | | | | 24,695 | | | |
| Parking Lots - Asphalt (ph 2) | | | | | | | | 18,151 | | |
| Parking Lots - Asphalt (ph 3) | | | | | | | | , - | 26,485 | |
| Parking Lots - Curb and Gutters Ph 1 | | | | | | | | | -, -, | |
| Parking Lots -Curb and Gutters Ph 2 | | | | | | | | | | |
| Parking Lots - Curb and Gutters Ph 3 | | | | | | | | | | |
| Parking Lots - Sealcoating/striping | 4,894 | | | 5,348 | | | 5,843 | | | 6,385 |
| Irrigation - Valve Boxes, Replace | 1,001 | | | 0,010 | | | 0,010 | | | 0,000 |
| Irrigation - Backflow Preventer, Replace | | 3,800 | | | | | 6,021 | | | + |
| Irrigation - Controller/Clock, Replace | | 3,000 | | | | | 1,469 | | | + |
| Landscaping - Trees/Shrubs (ph 1) | | | | | | | 3,671 | | | |
| Landscaping - Trees/Shrubs (ph 1) Landscaping - Trees/Shrubs (ph 2) | | | | | | | 3,071 | 3,025 | | |
| Landscaping - Trees/Shrubs (ph 2) Landscaping - Threes/shrubs (ph 3) | | | | | | | | 3,025 | 2.440 | |
| Landscaping - Threes/shrubs (ph 3) Lighting - walkways Ph 1 | | | | | | | | | 3,116 | |
| Lighting - Walkways Ph 1 | | | | | | | | | | |
| Lighting - walkways Ph 2 | | | | | | | | | | |
| Lighting - walkways Ph 3 | | | | | | | | | | _ |
| Sidewalks - concrete (ph 1) | | | | | | | | | | <u> </u> |
| Sidewalks - concrete (ph 2) | | | | | | | | | | _ |
| Sidewalks - concrete (ph 3) | | | | | | | | | | |
| Dumpster Enclsoures - Stain/power wash | 982 | | | 1,073 | | | 1,173 | | | 1,282 |
| Dumpster Enclsoure - Replace (Ph 1) | | | | | | | 7,343 | | | |
| Dumpster Enclosure - Replace Ph 2 | | | | | | | | 7,563 | | |
| Dumpster Enclosure - Replace Ph 3 | | | | | | | | | 7,790 | |
| Entryway sign - Replace | | | | | | | | | | |
| Dryer Vents - Clean out | 1,181 | | | 1,290 | | | 1,410 | | | 1,541 |
| | | | | | | | | | | |
| Estimated Total Cost | \$31,654 | \$32,955 | \$19,572 | \$11,763 | \$0 | \$39,943 | \$80,995 | \$69,602 | \$37,391 | \$14,046 |
| _sumated Total Cost | φ31,004 | φ3 ∠ ,933 | φ13,372 | φιι,/03 | φυ | φυ υ,υ4 υ | φου,990 | φυσ,002 | मुठा, उष्टा | φ14,040 |
| Annual Cash Balances | | | | | | | | | | |
| Beginning Cash Balance | \$285,912 | \$290,231 | \$294,425 | \$313,185 | \$342,303 | \$383,374 | \$387,090 | \$349,606 | \$323,913 | \$330,637 |
| Reserve Contribution | \$35,974 | \$37,149 | \$38,331 | \$40,881 | \$41,071 | \$43,659 | \$43,511 | \$43,909 | \$44,115 | \$47,371 |
| Interest Income | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Expenditures | \$31,654 | \$32,955 | \$19,572 | \$11,763 | \$0 | \$39,943 | \$80,995 | \$69,602 | \$37,391 | \$14,046 |
| Ending Cash Balance | \$290,231 | \$294,425 | \$313,185 | \$342,303 | \$383,374 | \$387,090 | \$349,606 | \$323,913 | \$330,637 | \$363,962 |
| Ending Cash Balance | Ψ230,231 | Ψ 2 .37,723 | ψυ10,100 | ψυτ2,υυυ | ψ505,574 | Ψ301,030 | ψυτυ,000 | Ψυ2υ,310 | ψοσο,σοι | ψ505,302 |
| | | | | | | | | | | |

| Component Name | 17 2028 | 18 2029 | 19 2030 | 20 2031 | 21 2032 | 22 2033 | 23 2034 | 24 2035 | 25 2036 | 26 2037 |
|---|-------------------|-------------------|-------------------|-------------------|-------------------|---|-------------------|-------------------|-------------------|-------------------|
| Painting - Bldg, Doors, Trim (ph1) | 18,181 | 42,561 | | | | | | 50,820 | | |
| Painting - Bldg, Doors, Trim (ph2) | .0,.0. | .2,00 | 35,070 | | | | | 00,020 | 41,876 | 43,132 |
| Painting - Bldg, Doors, Trim (ph 3) | | | 00,0.0 | 36,122 | | | | | , | , |
| Painting - Seal/Stain Decks | | 5,133 | | 5,445 | | 5,777 | | 6,129 | | 6,502 |
| Roofing - Ph 1 | | 0,100 | | 0,110 | | 0,111 | 35,525 | 0,120 | | - 0,002 |
| Roofing Ph 2 | | | | | | | 00,020 | 36,590 | | |
| Roofing Ph 3 | | | | | | | | 00,000 | 37,688 | |
| Gutters - Additions/Repair/Rep | | | 7,014 | | | | | 8,131 | 37,000 | |
| Lighting - Stairwell/Hallways Ph 1 | | | 7,014 | | | | 11,842 | 0,131 | | |
| Lighting - Stairwell/Hallways Ph 2 | | | | | | | 11,042 | 10,164 | | |
| Lighting - Stairwell/Hallways Ph 3 | | | | | | | | 10,104 | 10,469 | |
| Carpeting - Outdoor Stairwell, Replace | | | | | | | | | 23,032 | |
| Parking Lots - asphalt (ph 1) | | | | | | | | | 23,032 | |
| | | | | | | | | | | |
| Parking Lots - Asphalt (ph 2) Parking Lots - Asphalt (ph 3) | | | | | | | | | | |
| | | | | | | | 25 525 | | | |
| Parking Lots - Curb and Gutters Ph 1 | | | | | | | 35,525 | 00.400 | | |
| Parking Lots -Curb and Gutters Ph 2 | | | | | | | | 30,492 | 27.000 | |
| Parking Lots - Curb and Gutters Ph 3 | | | | | | | | | 37,688 | |
| Parking Lots - Sealcoating/striping | | | 6,977 | | | 7,624 | | | 8,331 | |
| Irrigation - Valve Boxes, Replace | | | | | | | 8,092 | | | |
| Irrigation - Backflow Preventer, Replace | | | | | | | 5,921 | | | |
| Irrigation - Controller/Clock, Replace | | | | | | | 1,974 | | | |
| Landscaping - Trees/Shrubs (ph 1) | | | | | | | | | | |
| Landscaping - Trees/Shrubs (ph 2) | | | | | | | 4,934 | 4,066 | | |
| Landscaping - Threes/shrubs (ph 3) | | | | | | | | | 4,188 | |
| Lighting - walkways Ph 1 | | | | | | | 7,894 | | | |
| Lighting - walkways Ph 2 | | | | | | | | 8,131 | | |
| Lighting - walkways Ph 3 | | | | | | | 35,525 | | 8,375 | |
| Sidewalks - concrete (ph 1) | | | | | | | | | | |
| Sidewalks - concrete (ph 2) | | | | | | | | 30,492 | | |
| Sidewalks - concrete (ph 3) | | | | | | | | | 37,688 | |
| Dumpster Enclsoures - Stain/power wash | | | 1,401 | | | 1,530 | | | 1,672 | |
| Dumpster Enclsoure - Replace (Ph 1) | | | , | | | , | | | , | |
| Dumpster Enclosure - Replace Ph 2 | | | | | | | | | | |
| Dumpster Enclosure - Replace Ph 3 | | | | | | | | | | |
| Entryway sign - Replace | | | | | | | 8,881.12 | | | - |
| Dryer Vents - Clean out | | | 1,683.35 | | | 1,839.45 | 5,55111 | | 2010.01 | |
| , | | | , | | | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | | | |
| Estimated Total Cost | \$18,181 | \$47,694 | \$52,145 | \$41,568 | \$0 | \$16,771 | \$156,111 | \$185,015 | \$213,016 | \$49,634 |
| Annual Cash Balances | | | | | | | | | | |
| Beginning Cash Balance | \$363,962 | \$395,589 | \$399,199 | \$398,973 | \$412,105 | \$466,412 | \$508,664 | \$412,491 | \$283,797 | \$126,682 |
| Degining Cash Balance | | | | | | | | | | |
| | \$49,808 | \$51,304 | \$51,920 | \$54,699 | \$54,307 | \$59,023 | \$59,938 | \$56,321 | \$55,901 | \$60,885 |
| Interest Income | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Expenditures | \$18,181 | \$47,694 | \$52,145 | \$41,568 | \$0 | \$16,771 | \$156,111 | \$185,015 | \$213,016 | \$49,634 |
| Ending Cash Balance | \$395,589 | \$399,199 | \$398,973 | \$412,105 | \$466,412 | \$508,664 | \$412,491 | \$283,797 | \$126,682 | \$137,933 |
| | | | | | | | | | | |

| | 27 | 28 | 29 |
|--|----------|----------|----------|
| Component Name | 2038 | 2039 | 2040 |
| Painting - Bldg, Doors, Trim (ph1) | 2000 | 2003 | 2040 |
| Painting - Bldg, Doors, Trim (ph1) | | | |
| Painting - Bidg, Doors, Trim (ph 3) | | | |
| | | 6000.1 | |
| Painting - Seal/Stain Decks | | 6898.1 | |
| Roofing - Ph 1 | | | |
| Roofing Ph 2 | | | |
| Roofing Ph 3 | | | 0.400.05 |
| Gutters - Additions/Repair/Rep | | | 9426.25 |
| Lighting - Stairwell/Hallways Ph 1 | | | |
| Lighting - Stairwell/Hallways Ph 2 | | | |
| Lighting - Stairwell/Hallways Ph 3 | | | |
| Carpeting - Outdoor Stairwell, Replace | | | |
| Parking Lots - asphalt (ph 1) | | | |
| Parking Lots - Asphalt (ph 2) | | | |
| Parking Lots - Asphalt (ph 3) | | | |
| Parking Lots - Curb and Gutters Ph 1 | | | |
| Parking Lots -Curb and Gutters Ph 2 | | | |
| Parking Lots - Curb and Gutters Ph 3 | | | |
| Parking Lots - Sealcoating/striping | | 9103.8 | |
| Irrigation - Valve Boxes, Replace | | | |
| Irrigation - Backflow Preventer, Replace | | | |
| Irrigation - Controller/Clock, Replace | | | |
| Landscaping - Trees/Shrubs (ph 1) | | | |
| Landscaping - Trees/Shrubs (ph 2) | | | |
| Landscaping - Threes/shrubs (ph 3) | | | |
| Lighting - walkways Ph 1 | | | |
| Lighting - walkways Ph 2 | | | |
| Lighting - walkways Ph 3 | | | |
| Sidewalks - concrete (ph 1) | | | |
| Sidewalks - concrete (ph 2) | | | |
| Sidewalks - concrete (ph 3) | | | |
| Dumpster Enclsoures - Stain/power wash | | 1827.45 | |
| Dumpster Enclsoure - Replace (Ph 1) | | | |
| Dumpster Enclosure - Replace Ph 2 | | | |
| Dumpster Enclosure - Replace Ph 3 | | | |
| Entryway sign - Replace | | | |
| Dryer Vents - Clean out | | 2196.39 | |
| | | | |
| | | | |
| | | | |
| | | 1 | |
| | | | |
| | | | |
| | | | |
| <u> </u> | ¢50.447 | #67.000 | ¢60 C00 |
| | \$59,147 | \$67,368 | \$68,693 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |