

## ENGLERT WEATHERTIGHTNESS INSPECTION

Project: <u>Cuthbert Amphitheater</u>	Installation Contractor: <u>Southam and Association</u>
Location: <u>555 Day 1 Sland Rd. Eugene, OR 97401</u>	Location: <u>572 East 1700 South American Fork, UT 84003</u>
General Contractor: <u>McKenzie Commercial</u>	Contact: <u>Cory Walker : 801-318-7937</u>
Date of Inspection: <u>2/28/14</u>	Site Telephone (Include Area Code): _____
Roof System: <u>Series 1300 and 90 degree seam</u>	Project Progress At Inspection: <u>panel Installation</u>
Roof Color: _____	Roof Square Footage: <u>9,075 Sq.Ft.</u>
	Panel Width/Gauge: _____

### MATCH APPROVED SHOP DRAWINGS WITH CURRENT SITE CONDITIONS

*Photograph	Detail	As Detailed	Variation	Approved	Rejected	See Notes
	Side/Head Wall					
X	Rake/Gable Condition	X		X		1
X X	Eave Condition	X X		X X		1
X	Ridge/Hip Condition	X X		X X		1
X	Peak Condition	X X		X X		1
	Pipe Penetrations					
	Curb Flashings					
	Valley Conditions					
X X	Clip type & Fasteners	X		X X		3
	Underlayment (HT-60)	X		X X		
	Deck Condition					
X	Panel Profile	X		X		2
	Other: Solar Thermal System					
	Other: Expansion Joint					

\*Provide (1) Clear, Close, 35mm Photograph Of Each Detail, & A Maximum Of (2) Long Shots Of The Overall Project For Reference.

### GENERAL NOTES

- 1) ALL DETAILS NICELY AND CONSISTENTLY DONE

2) CONSISTENT AND VERY APPEALING TO THE EYE

3) VISIBLE FASTENERS EVENLY SPACED, FLUSH & PERPENDICULAR

\* SECURE ALL 'DIAMONDS' ON FRONT FACE OF PEAK CAP

\* SCRAPE AND CLEAN MISC AREAS OF CAULK EXCESS

Additional Inspections Required?	Yes No <input checked="" type="checkbox"/>
*Reason: _____	
Reinspection Of Rejected Details Required?	Yes No <input checked="" type="checkbox"/>
*Reason: _____	
Date: <u>3/1/14</u>	Inspector: <u>JOE SARDOTZ • OREGON ROOF CONSULTING</u>

INSPECTION COMPLETED. SUMMARY AND PHOTO DOCUMENTATION PROVIDED. VERY NICE INSTALL ON A UNIQUE AND CHALLENGING PROJECT!  
IT WAS A PLEASURE TO PARTICIPATE IN THIS PROJECT!

*Joe Sardotz*